

# Intercept the Grease

☘ Check grease thickness regularly

☘ 定期檢查油脂厚度

☘ Grease thickness and solids depth should be less than 25% of the total depth of the interceptor


☘ 油脂的厚度和固態物的深度應在截離器總深度的25%以下

☘ Have a licensed hauler pump out and clean your interceptor regularly

☘ 請有執照的業者定期抽取油脂並清潔油脂截離器

☘ Check solids depth regularly

☘ 定期檢查固態物的深度



City of Los Angeles / Department of Public Works / Bureau of Sanitation / Industrial Waste Management Division

For more information call: 323-342-6200 or visit: [www.lacitysan.org](http://www.lacitysan.org)



Printed on recycled paper.